


ZERO Calibration

The meter only supports pure water calibration

1. Drop 0.2-0.3ml pure water then close the cover to measure.

Press "cal" button for 2 seconds to enter the calibration status Press "CAL" button for 2-3 seconds till see the CAL flashing.



2. Press the "CAL" button again during CAL flashing to start calibration. The left image is displayed after the calibration is completed.

If there is no operation for 10 seconds, the instrument will return to the startup state.

If fail to complete the calibration, multi-function display area would show an error code



2 MEASUREMENT MODES

3 seconds fast measurement data

Brix measurement



Extraction rate measurement

