

# **TECHNICAL DATA SHEET**

### Name: Thermometer Indoor/Outdoor Digital

**Reference** 206815



**General Description:** Digital thermometer with indoor and outdoor temperature, humidity, and time display.

Country of Manufacture: China

**Storage:** Store in a dry environment. Keep away from direct sunlight.

## **Packaging Configuration:**

Unit: 1pce - Blister pack.

Barcode: 9417027103934.

Weight/Volume/Dimensions: estimated weight: 0.101kg estimated volume: 0.663cdm

### **Technical Specifications:**

- Indoor-outdoor thermometer
- Indoor hygrometer (humidity)
- Desk-top placing or wall hanging
- Large multi-function LCD display
- Selectable degree °C & °F
- Memory of MAX & MIN temperature
- Indoor & Outdoor Temperature -10 ~ +70°C (14~ +158°F)
- Temperature Accuracy +/-1°C (1.8°F)
- Outdoor cable length 1.4 metre
- Humidity range: 10% ~ 99% RH
- Humidity accuracy: -/+5% RH
- 12-hour / 24-hour time display
- Selectable clock & date function (month and date)
- Alarm function
- Hourly chime function
- Power supply: 1x 1.5V Battery (AAA size)

#### Instructions for use:

Open battery compartment and insert battery. Orient battery as per +/- symbols.

#### Key Functions:

- MODE Switches clock, alarm clock, display modes and set current time, alarm time, 12/24-hour clock and date.
- ADJ Adjusts values of set items.
- MEM Display & reset minimum or maximum temperature or humidity values in memory, switch between Celsius and Fahrenheit

Press and hold MODE key for 2 seconds to make minute value in current time flash. Use ADJ key to set. Press MODE key to progress to hour value, before progressing to month/day.

Press MEM key to display memorised MAX & MIN values of temperature & humidity. Hold MEM key for 2 seconds to reset.